



Énergie NB Power

the power of possibility
débordant d'énergie

Mini-Split Heat Pumps - List of Eligible Models May 2022

| AHRI Reference Number | Brand | Outdoor Model | Indoor Model | Outside Operating Temperature (-25C or colder) |
|-----------------------|-------------------|----------------------|----------------------|--|
| 201863350 | ACD | OCD09KCH23S-O | OCD09KCH23S-I | -25 |
| 201863351 | ACD | OCD12KCH22S-O | OCD12KCH22S-I | -25 |
| 201863352 | ACD | OCD18KCH20S-O | OCD18KCH20S-I | -25 |
| 201863353 | ACD | OCD24KCH20S-O | OCD24KCH20S-I | -25 |
| 206703383 | ACD | OCD15KCH20S-O | OCD15KCH20S-I | -25 |
| 202110483 | ACD/Ouelllet | UHD09KCH38S-O | UHD09KCH38S-I | -30 |
| 202110484 | ACD/Ouelllet | UHD12KCH31S-O | UHD12KCH31S-I | -30 |
| 202110485 | ACD/Ouelllet | UHD18KCH25S-O | UHD18KCH25S-I | -30 |
| 202132789 | ACD/Ouelllet | UHD24KCH22S-O | UHD24KCH22S-I | -30 |
| 202409832 | ACD/Ouelllet | UHD09KCH38SB-O | UHD09KCH38SB-I | -30 |
| 9150122 | AMERICAN STANDARD | 4TXK3809A10NU** | 4MXW3809A10NU** | -30 |
| 8177085 | ARCOAIRE | DLCAHB09K1A | DLFAHH09K1A | -30 |
| 8177094 | ARCOAIRE | DLCAHB12K1A | DLFAHH12K1A | -30 |
| 8177103 | ARCOAIRE | DLCAHB18K1A | DLFAHH18K1A | -30 |
| 201835506 | ARCOAIRE | DLCPRAH09AAK | DLFPAH09XAK | -25 |
| 201835507 | ARCOAIRE | DLCPRAH12AAK | DLFPAH12XAK | -25 |
| 201835513 | ARCOAIRE | DLCSRAH09AAJ | DLFSAH09XAJ | -25 |
| 201835514 | ARCOAIRE | DLCSRAH12AAJ | DLFSAH12XAJ | -25 |
| 201835515 | ARCOAIRE | DLCSRAH09AAK | DLFSAH09XAK | -25 |
| 201835516 | ARCOAIRE | DLCSRAH12AAK | DLFSAH12XAK | -25 |
| 201835517 | ARCOAIRE | DLCSRAH18AAK | DLFSAH18XAK | -25 |
| 201835518 | ARCOAIRE | DLCSRAH24AAK | DLFSAH24XAK | -25 |
| 201835531 | ARCOAIRE | DLCSRAH09AAK | DLFSDAH09XAK | -25 |
| 201835532 | ARCOAIRE | DLCSRAH09AAK | DLFSCAH09XAK | -25 |
| 201835533 | ARCOAIRE | DLCSRAH12AAK | DLFSCAH12XAK | -25 |
| 201835534 | ARCOAIRE | DLCSRAH12AAK | DLFSFAH12XAK | -25 |
| 201835535 | ARCOAIRE | DLCSRAH12AAK | DLFSDAH12XAK | -25 |
| 201835536 | ARCOAIRE | DLCSRAH18AAK | DLFSFAH18XAK | -25 |
| 201835537 | ARCOAIRE | DLCSRAH18AAK | DLFSCAH18XAK | -25 |
| 201835538 | ARCOAIRE | DLCSRAH24AAK | DLFSDAH24XAK | -25 |
| 201835543 | ARCOAIRE | DLCSRAH18AAK | DLFSDAH18XAK | -25 |
| 203991147 | BOSCH | BMS500-AAS012-0CSXRB | BMS500-AAS012-0AHWXB | -25 |
| 203991148 | BOSCH | BMS500-AAS009-1CSXRA | BMS500-AAU009-1AHWXB | -25 |
| 203991149 | BOSCH | BMS500-AAS012-1CSXRA | BMS500-AAU012-1AHWXB | -25 |
| 203991150 | BOSCH | BMS500-AAS018-1CSXRA | BMS500-AAU018-1AHWXB | -25 |
| 203991151 | BOSCH | BMS500-AAS024-1CSXRA | BMS500-AAU024-1AHWXB | -25 |

| | | | | |
|-----------|--------|----------------------|----------------------|-----|
| 203991152 | BOSCH | BMS500-AAS009-1CSXHB | BMS500-AAU009-1AHWXB | -30 |
| 203991153 | BOSCH | BMS500-AAS012-1CSXHB | BMS500-AAU012-1AHWXB | -30 |
| 203991154 | BOSCH | BMS500-AAS018-1CSXHB | BMS500-AAU018-1AHWXB | -30 |
| 203991155 | BOSCH | BMS500-AAS024-1CSXHB | BMS500-AAU024-1AHWXB | -30 |
| 203991159 | BOSCH | BMS500-AAS009-1CSXRA | BMS500-AAU009-1AHDXB | -25 |
| 203991160 | BOSCH | BMS500-AAS012-1CSXRA | BMS500-AAU012-1AHDXB | -25 |
| 203991161 | BOSCH | BMS500-AAS018-1CSXRA | BMS500-AAU018-1AHDXB | -25 |
| 203991162 | BOSCH | BMS500-AAS024-1CSXRA | BMS500-AAU024-1AHDXB | -25 |
| 203991166 | BOSCH | BMS500-AAS009-1CSXRA | BMS500-AAU009-1AHCXB | -25 |
| 203991167 | BOSCH | BMS500-AAS012-1CSXRA | BMS500-AAU012-1AHCXB | -25 |
| 203991168 | BOSCH | BMS500-AAS018-1CSXRA | BMS500-AAU018-1AHCXB | -25 |
| 203991169 | BOSCH | BMS500-AAS024-1CSXRA | BMS500-AAU024-1AHCXB | -25 |
| 204014464 | BOSCH | BMS500-AAS009-1CSXHB | BMS500-AAU009-1AHCXB | -30 |
| 204014465 | BOSCH | BMS500-AAS012-1CSXHB | BMS500-AAU012-1AHCXB | -30 |
| 204014466 | BOSCH | BMS500-AAS018-1CSXHB | BMS500-AAU018-1AHCXB | -30 |
| 204014467 | BOSCH | BMS500-AAS009-1CSXHB | BMS500-AAU009-1AHDXB | -30 |
| 204014468 | BOSCH | BMS500-AAS012-1CSXHB | BMS500-AAU012-1AHDXB | -30 |
| 204014469 | BOSCH | BMS500-AAS018-1CSXHB | BMS500-AAU018-1AHDXB | -30 |
| 204014470 | BOSCH | BMS500-AAS024-1CSXHB | BMS500-AAU024-1AHDXB | -30 |
| 205921394 | BOSCH | BMS500-AAS012-1CSXXA | BMS500-AAU012-1AHWXB | -25 |
| 8016597 | BRYANT | 538FEQ009RBGAAAA | 619FEQ009BBGAAAA | -30 |
| 8016598 | BRYANT | 538FEQ009RBGAAAA | 619FEQ009HBGAAAA | -30 |
| 8177080 | BRYANT | DLCAHB09K1A | DLFAHH09K1A | -30 |
| 8177089 | BRYANT | DLCAHB12K1A | DLFAHH12K1A | -30 |
| 8177098 | BRYANT | DLCAHB18K1A | DLFAHH18K1A | -30 |
| 8738643 | BRYANT | 38MAQB24R--3 | 619PEQ024BBMA | -30 |
| 8738644 | BRYANT | 38MAQB18R--3 | 619PEQ018BBMA | -30 |
| 8738645 | BRYANT | 38MAQB12R--3 | 619PEQ012BBMA | -30 |
| 8738646 | BRYANT | 38MAQB09R--3 | 619PEQ009BBMA | -30 |
| 8738647 | BRYANT | 38MAQB12R--1 | 619PAQ012BBMA | -25 |
| 8738648 | BRYANT | 38MAQB09R--1 | 619PAQ009BBMA | -25 |
| 8856640 | BRYANT | 38MAQB09R--3 | 619REQ009DBMA | -30 |
| 8856641 | BRYANT | 38MAQB09R--3 | 619REQ009CBMA | -30 |
| 8856642 | BRYANT | 38MAQB09R--3 | 619REQ009FBMA | -30 |
| 8856646 | BRYANT | 38MAQB12R--3 | 619REQ012DBMA | -30 |
| 8856647 | BRYANT | 38MAQB12R--3 | 619REQ012CBMA | -30 |
| 8856648 | BRYANT | 38MAQB12R--3 | 619REQ012FBMA | -30 |
| 8856652 | BRYANT | 38MAQB18R--3 | 619REQ018DBMA | -30 |
| 8856654 | BRYANT | 38MAQB18R--3 | 619REQ018CBMA | -30 |
| 8856656 | BRYANT | 38MAQB24R--3 | 619REQ024DBMA | -25 |
| 200059142 | BRYANT | 38MAQB18R--3 | 40MBDQ18---3 | -25 |
| 200059144 | BRYANT | 38MAQB24R--3 | 40MBDQ24---3 | -25 |
| 200059150 | BRYANT | 38MAQB09R--3 | 40MBCQ09---3 | -25 |
| 200059152 | BRYANT | 38MAQB09R--3 | 40MBFQ09---3 | -30 |
| 200059154 | BRYANT | 38MAQB12R--3 | 40MBCQ12---3 | -25 |
| 200059156 | BRYANT | 38MAQB12R--3 | 40MBFQ12---3 | -25 |
| 200059158 | BRYANT | 38MAQB18R--3 | 40MBCQ18---3 | -25 |

| | | | | |
|-----------|---------|------------------|------------------|-----|
| 201753409 | BRYANT | 38MPRAQ09AA3 | 619PHAQ09XA3 | -25 |
| 201753412 | BRYANT | 38MPRAQ12AA3 | 619PHAQ12XA3 | -25 |
| 201846963 | BRYANT | 38MAQB09R--3 | 40MBDQ09---3 | -25 |
| 201846964 | BRYANT | 38MAQB12R--3 | 40MBDQ12---3 | -25 |
| 201846965 | BRYANT | 38MAQB18R--3 | 40MBFQ18---3 | -25 |
| 206188260 | BRYANT | 38MARBQ24AA3 | 40MBAAQ24XA3 | -30 |
| 206350347 | BRYANT | 38MARBQ24AA3 | 40MBDQ24---3 | -30 |
| 206348144 | BRYANT | 38MARBQ18AA3 | 619AHBQ18XA3 | -30 |
| 206350343 | BRYANT | 38MARBQ18AA3 | 40MBCQ18---3 | -30 |
| 206350344 | BRYANT | 38MARBQ18AA3 | 40MBDQ18---3 | -30 |
| 206350345 | BRYANT | 38MARBQ18AA3 | 40MBFQ18---3 | -30 |
| 206400650 | BRYANT | 38MARBQ18AA3 | 619PEQ018BBMA | -30 |
| 206350340 | BRYANT | 38MARBQ12AA3 | 40MBCQ12---3 | -30 |
| 7947236 | CARRIER | 38MAQB12---101-- | 40MAQB12B--101-- | -25 |
| 7947238 | CARRIER | 38MAQB12---301-- | 40MAQB12B--301-- | -25 |
| 7947277 | CARRIER | 38MAQB12---301-- | 40MBQB12C--301-- | -25 |
| 7947287 | CARRIER | 38MAQB12---301-- | 40MBQB12F--301-- | -25 |
| 7992953 | CARRIER | 38GRQB09---301-- | 40GRQB09B--301-- | -30 |
| 7992954 | CARRIER | 38GRQB09---301-- | 40GRQB09H--301-- | -30 |
| 7992955 | CARRIER | 38GRQB12---301-- | 40GRQB12B--301-- | -30 |
| 7992956 | CARRIER | 38GRQB12---301-- | 40GRQB12H--301-- | -30 |
| 7992957 | CARRIER | 38GRQB18---301-- | 40GRQB18B--301-- | -30 |
| 7992958 | CARRIER | 38GRQB18---301-- | 40GRQB18H--301-- | -30 |
| 8016604 | CARRIER | 38MAQB12---301-- | 40MBQB12D--301-- | -25 |
| 8738633 | CARRIER | 38MAQB09R--1 | 40MAQB09B--1 | -25 |
| 8738634 | CARRIER | 38MAQB12R--1 | 40MAQB12B--1 | -25 |
| 8738635 | CARRIER | 38MAQB09R--3 | 40MAQB09B--3 | -30 |
| 8738636 | CARRIER | 38MAQB12R--3 | 40MAQB12B--3 | -30 |
| 8738637 | CARRIER | 38MAQB18R--3 | 40MAQB18B--3 | -30 |
| 8738638 | CARRIER | 38MAQB24R--3 | 40MAQB24B--3 | -30 |
| 8856643 | CARRIER | 38MAQB09R--3 | 40MBQB09D--3 | -25 |
| 8856644 | CARRIER | 38MAQB09R--3 | 40MBQB09C--3 | -30 |
| 8856645 | CARRIER | 38MAQB09R--3 | 40MBQB09F--3 | -30 |
| 8856649 | CARRIER | 38MAQB12R--3 | 40MBQB12F--3 | -30 |
| 8856650 | CARRIER | 38MAQB12R--3 | 40MBQB12D--3 | -25 |
| 8856651 | CARRIER | 38MAQB12R--3 | 40MBQB12C--3 | -30 |
| 8856653 | CARRIER | 38MAQB18R--3 | 40MBQB18D--3 | -25 |
| 8856655 | CARRIER | 38MAQB18R--3 | 40MBQB18C--3 | -30 |
| 8856657 | CARRIER | 38MAQB24R--3 | 40MBQB24D--3 | -25 |
| 200059143 | CARRIER | 38MAQB18R--3 | 40MBDQ18---3 | -25 |
| 200059145 | CARRIER | 38MAQB24R--3 | 40MBDQ24---3 | -25 |
| 200059151 | CARRIER | 38MAQB09R--3 | 40MBCQ09---3 | -25 |
| 200059153 | CARRIER | 38MAQB09R--3 | 40MBFQ09---3 | -25 |
| 200059155 | CARRIER | 38MAQB12R--3 | 40MBCQ12---3 | -25 |
| 200059157 | CARRIER | 38MAQB12R--3 | 40MBFQ12---3 | -25 |
| 200059159 | CARRIER | 38MAQB18R--3 | 40MBCQ18---3 | -25 |
| 201753408 | CARRIER | 38MPRAQ09AA3 | 40MPHAQ09XA3 | -30 |

| | | | | |
|-----------|--------------------------------|--------------------|--------------------|-----|
| 201753411 | CARRIER | 38MPRAQ12AA3 | 40MPHAQ12XA3 | -30 |
| 201846960 | CARRIER | 38MAQB09R--3 | 40MBDQ09---3 | -25 |
| 201846961 | CARRIER | 38MAQB12R--3 | 40MBDQ12---3 | -25 |
| 201846962 | CARRIER | 38MAQB18R--3 | 40MBFQ18---3 | -25 |
| 202463634 | CARRIER | 38MPRAQ18AA3 | 40MPHAQ18XA3 | -30 |
| 206188253 | CARRIER | 38MARBQ24AA3 | 40MBAAQ24XA3 | -30 |
| 206350336 | CARRIER | 38MARBQ24AA3 | 40MBDQ24---3 | -30 |
| 206348137 | CARRIER | 38MARBQ18AA3 | 40MAHBQ18XA3 | -30 |
| 206350332 | CARRIER | 38MARBQ18AA3 | 40MBCQ18---3 | -30 |
| 206350333 | CARRIER | 38MARBQ18AA3 | 40MBDQ18---3 | -30 |
| 206350334 | CARRIER | 38MARBQ18AA3 | 40MBFQ18---3 | -30 |
| 206400644 | CARRIER | 38MARBQ18AA3 | 40MAQB18B--3 | -30 |
| 206350329 | CARRIER | 38MARBQ12AA3 | 40MBCQ12---3 | -30 |
| 200059036 | CENTURY | A-VMH24SU-1 | B-VMH24SU-1 | -30 |
| 200059038 | CENTURY | A-VMH18SU-1 | B-VMH18SU-1 | -30 |
| 200059040 | CENTURY | A-VMH12SU-1 | B-VMH12SU-1 | -30 |
| 200059042 | CENTURY | A-VMH09SU-1 | B-VMH09SU-1 | -30 |
| 8657820 | CHAMPION | DHZ09CSB21S | DHZ09NWB21S | -30 |
| 8657822 | CHAMPION | DHZ12CSB21S | DHZ12NWB21S | -30 |
| 8657824 | CHAMPION | DHZ18CSB21S | DHZ18NWB21S | -30 |
| 8578586 | COLEMAN BY JOHNSON CONTROLS | DHZ09CSB21S | DHZ09NWB21S | -30 |
| 8578590 | COLEMAN BY JOHNSON CONTROLS | DHZ12CSB21S | DHZ12NWB21S | -30 |
| 8578594 | COLEMAN BY JOHNSON CONTROLS | DHZ18CSB21S | DHZ18NWB21S | -30 |
| 200059045 | COMFEE | MOCA30-18HFN1-MTOW | CS11M-18HRFN1-MTOW | -25 |
| 200059048 | COMFEE | MOD30-24HFN1-MTOW | CS11M-23HRFN1-MTOW | -25 |
| 200059035 | COMFORT-AIRE | A-VMH24SU-1 | B-VMH24SU-1 | -30 |
| 200059037 | COMFORT-AIRE | A-VMH18SU-1 | B-VMH18SU-1 | -30 |
| 200059039 | COMFORT-AIRE | A-VMH12SU-1 | B-VMH12SU-1 | -30 |
| 200059041 | COMFORT-AIRE | A-VMH09SU-1 | B-VMH09SU-1 | -30 |
| 201810040 | COMFORT-AIRE | A-VMH18SU-1A | B-VMH18SU-1A | -30 |
| 205747696 | COMFORT-AIRE | A-VMH18SU-1B | B-VMH18SU-1B | -30 |
| 206221394 | COMFORT-AIRE | A-VMH24SU-1A | B-VMH24SU-1A | -30 |
| 207657385 | COMFORT-AIRE | A-VMH06SV-1 | B-VMH06SV-1 | -30 |
| 207657386 | COMFORT-AIRE | A-VMH09SV-1 | B-VMH09SV-1 | -30 |
| 207657387 | COMFORT-AIRE | A-VMH12SV-1 | B-VMH12SV-1 | -30 |
| 207657388 | COMFORT-AIRE | A-VMH18SV-1 | B-VMH18SV-1 | -30 |
| 207657389 | COMFORT-AIRE | A-VMH24SV-1 | B-VMH24SV-1 | -30 |
| 8177087 | COMFORTMAKER | DLC AHB09K1A | DLFAHH09K1A | -30 |
| 8177096 | COMFORTMAKER | DLC AHB12K1A | DLFAHH12K1A | -30 |
| 8177105 | COMFORTMAKER | DLC AHB18K1A | DLFAHH18K1A | -30 |
| 201835554 | COMFORTMAKER | DLC PRAH09AAK | DLFPAH09XAK | -25 |
| 201835555 | COMFORTMAKER | DLC PRAH12AAK | DLFPAH12XAK | -25 |
| 201835561 | COMFORTMAKER | DLC SRAH09AAJ | DLFSAH09XAJ | -25 |
| 201835562 | COMFORTMAKER | DLC SRAH12AAJ | DLFSAH12XAJ | -25 |

| | | | | |
|-----------|--------------|--------------|--------------|-----|
| 201835563 | COMFORTMAKER | DLCSRAH09AAK | DLFSHAH09XAK | -25 |
| 201835564 | COMFORTMAKER | DLCSRAH12AAK | DLFSHAH12XAK | -25 |
| 201835565 | COMFORTMAKER | DLCSRAH18AAK | DLFSHAH18XAK | -25 |
| 201835566 | COMFORTMAKER | DLCSRAH24AAK | DLFSHAH24XAK | -25 |
| 201835580 | COMFORTMAKER | DLCSRAH09AAK | DLFSDAH09XAK | -25 |
| 201835581 | COMFORTMAKER | DLCSRAH09AAK | DLFSCAH09XAK | -25 |
| 201835582 | COMFORTMAKER | DLCSRAH12AAK | DLFSCAH12XAK | -25 |
| 201835583 | COMFORTMAKER | DLCSRAH12AAK | DLFSFAH12XAK | -25 |
| 201835584 | COMFORTMAKER | DLCSRAH12AAK | DLFSDAH12XAK | -25 |
| 201835585 | COMFORTMAKER | DLCSRAH18AAK | DLFSFAH18XAK | -25 |
| 201835586 | COMFORTMAKER | DLCSRAH18AAK | DLFSCAH18XAK | -25 |
| 201835587 | COMFORTMAKER | DLCSRAH24AAK | DLFSDAH24XAK | -25 |
| 201835592 | COMFORTMAKER | DLCSRAH18AAK | DLFSDAH18XAK | -25 |
| 206422436 | Convectair | 8090-O | 8090-I | -30 |
| 206422437 | Convectair | 8120-O | 8120-I | -30 |
| 206422438 | Convectair | 8180-O | 8180-I | -30 |
| 206422439 | Convectair | 8240-O | 8240-I | -30 |
| 207709204 | Convectair | 8028-C09-O | 8028-C09-I | -30 |
| 207709205 | Convectair | 8028-C12-O | 8028-C12-I | -30 |
| 207709206 | Convectair | 8028-C18-O | 8028-C18-I | -30 |
| 207709207 | Convectair | 8028-C24-O | 8028-C24-I | -30 |
| 5265753 | DAIKIN | RXS09LVJU | FTXS09LVJU | -25 |
| 5265755 | DAIKIN | RXS12LVJU | FTXS12LVJU | -25 |
| 5265756 | DAIKIN | RXS15LVJU | FTXS15LVJU | -25 |
| 5265757 | DAIKIN | RXS18LVJU | FTXS18LVJU | -25 |
| 5265758 | DAIKIN | RXS24LVJU | FTXS24LVJU | -25 |
| 8849451 | DAIKIN | RXL12QMVJU | FVXS12NVJU | -25 |
| 8849458 | DAIKIN | RXL12QMVJU | FTX12NMVJU | -25 |
| 8849330 | DAIKIN | RXL15QMVJU | FTX15NMVJU | -25 |
| 8849459 | DAIKIN | RXL09QMVJU | FVXS09NVJU | -25 |
| 8849533 | DAIKIN | RXL09QMVJU | FTX09NMVJU | -25 |
| 204717600 | DAIKIN | RXL12QMVJU9 | FTX12NMVJU | -25 |
| 204718024 | DAIKIN | RXL24UMVJU | FDMQ24RVJU | -25 |
| 205663349 | DAIKIN | RXL15QMVJU* | FTX15NMVJU | -25 |
| 205782845 | DAIKIN | RX09AXVJU | FTX09AXVJU | -25 |
| 205782846 | DAIKIN | RX12AXVJU | FTX12AXVJU | -25 |
| 8177084 | DAY & NIGHT | DLCAHB09K1A | DLFAHH09K1A | -30 |
| 8177093 | DAY & NIGHT | DLCAHB12K1A | DLFAHH12K1A | -30 |
| 8177102 | DAY & NIGHT | DLCAHB18K1A | DLFAHH18K1A | -30 |
| 201835602 | DAY & NIGHT | DLCPRAH09AAK | DLFPHAH09XAK | -25 |
| 201835603 | DAY & NIGHT | DLCPRAH12AAK | DLFPHAH12XAK | -25 |
| 201835609 | DAY & NIGHT | DLCSRAH09AAJ | DLFSHAH09XAJ | -25 |
| 201835610 | DAY & NIGHT | DLCSRAH12AAJ | DLFSHAH12XAJ | -25 |
| 201835611 | DAY & NIGHT | DLCSRAH09AAK | DLFSHAH09XAK | -25 |
| 201835612 | DAY & NIGHT | DLCSRAH12AAK | DLFSHAH12XAK | -25 |
| 201835613 | DAY & NIGHT | DLCSRAH18AAK | DLFSHAH18XAK | -25 |
| 201835614 | DAY & NIGHT | DLCSRAH24AAK | DLFSHAH24XAK | -25 |

| | | | | |
|-----------|-------------|--------------------|-----------------------|-----|
| 201835628 | DAY & NIGHT | DLCSRAH09AAK | DLFSDAH09XAK | -25 |
| 201835629 | DAY & NIGHT | DLCSRAH09AAK | DLFSCAH09XAK | -25 |
| 201835630 | DAY & NIGHT | DLCSRAH12AAK | DLFSCAH12XAK | -25 |
| 201835631 | DAY & NIGHT | DLCSRAH12AAK | DLFSFAH12XAK | -25 |
| 201835632 | DAY & NIGHT | DLCSRAH12AAK | DLFSDAH12XAK | -25 |
| 201835633 | DAY & NIGHT | DLCSRAH18AAK | DLFSFAH18XAK | -25 |
| 201835634 | DAY & NIGHT | DLCSRAH18AAK | DLFSCAH18XAK | -25 |
| 201835635 | DAY & NIGHT | DLCSRAH24AAK | DLFSDAH24XAK | -25 |
| 201835640 | DAY & NIGHT | DLCSRAH18AAK | DLFSDAH18XAK | -25 |
| 7084999 | DIRECT AIR | MOZ-09HFN1-MX4W | MS11M-09HRFN1-MX4W | -25 |
| 7085000 | DIRECT AIR | MOZ-12HFN1-MW0W | MS11M-12HRFN1-MW0W | -25 |
| 8775827 | DIRECT AIR | MOB30-12HFN1-MV0W | CS11M-12HRFN1-MU5W | -25 |
| 8775828 | DIRECT AIR | MOCA30-18HFN1-MT0W | CS11M-18HRFN1-MT0W | -25 |
| 8775829 | DIRECT AIR | MOD30-24HFN1-MT0W | CS11M-23HRFN1-MT0W | -25 |
| 206377760 | DIRECT AIR | MOX430-17HFN1-MT0W | MTIU-18HWFN1-M | -30 |
| 8775842 | DIRECT AIR | MOBA30-09HFN1-MT0W | CCA3U-09HRFN1-M(C) | -25 |
| 8775845 | DIRECT AIR | MOB30-12HFN1-MT0W | CCA3U-12HRFN1-M(C) | -25 |
| 8775849 | DIRECT AIR | MOCA31-18HFN1-MT0W | CCA3U-18HRFN1-M(C) | -25 |
| 8775852 | DIRECT AIR | MOD31-24HFN1-MT0W | MCDU-24HRFN1-M(C) | -25 |
| 9680947 | DIRECT AIR | MOBA30-09HFN1-MT0W | CS11M-09HRFN1-MX0W(A) | -25 |
| 9680948 | DIRECT AIR | MOB30-12HFN1-MT0W | CS11M-12HRFN1-MU5W | -25 |
| 9680949 | DIRECT AIR | MOCA31-18HFN1-MT0W | CS11M-18HRFN1-MT0W | -25 |
| 9680950 | DIRECT AIR | MOD31-24HFN1-MT0W | CS11M-23HRFN1-MT0W | -25 |
| 8952869 | DIRECT AIR | MOB30-09HFN1-MX0W | CS11M-09HRFN1-MX0W(A) | -30 |
| 8952870 | DIRECT AIR | MOB30-12HFN1-MV0W | CS11M-12HRFN1-MU5W | -30 |
| 205816491 | DIRECT AIR | MOX430-17HFN1-MT0W | CS11M-18HRFN1-MT0W | -30 |
| 8775850 | DIRECT AIR | MOCA31-18HFN1-MT0W | MUEU-18HRFN1-M(C) | -25 |
| 8775853 | DIRECT AIR | MOD31-24HFN1-MT0W | MUEU-24HRFN1-M(C) | -25 |
| 206377758 | DIRECT AIR | MOX430-17HFN1-MT0W | MUEU-18HRFN1-M(C) | -30 |
| 203238486 | ELIOS | DE09HOS23230E2 | DE09HIW23230E3 | -25 |
| 203238487 | ELIOS | DE12HOS23230E2 | DE12HIW23230E3 | -25 |
| 203238488 | ELIOS | DE18HOS23230E2 | DE18HIW23230E3 | -25 |
| 203238490 | ELIOS | DE24HOS23230E2 | DE24HIW23230E3 | -25 |
| 203238492 | ELIOS | DE09HOS23230E2 | DE09HIDU230X5 | -25 |
| 203238494 | ELIOS | DE12HOS23230E2 | DE12HIDU230X5 | -25 |
| 203238495 | ELIOS | DE18HOS23230E2 | DE18HIDU230X5 | -25 |
| 203238496 | ELIOS | DE24HOS23230E2 | DE24HIDU230X5 | -25 |
| 203238498 | ELIOS | DE09HOS23230E2 | DE09HICU230X5 | -25 |
| 203238499 | ELIOS | DE12HOS23230E2 | DE12HICU230X5 | -25 |
| 203238501 | ELIOS | DE18HOS23230E2 | DE18HICU230X5 | -25 |
| 203238503 | ELIOS | DE24HOS23230E2 | DE24HICU230X5 | -25 |
| 206401445 | ELIOS | DE18HOS25230E3A | DE18HIW23230E3 | -30 |
| 206401446 | ELIOS | DE18HOS25230E3A | DM18HIDU230X5 | -30 |
| 206401447 | ELIOS | DE18HOS25230E3A | DM18HICU230X5 | -30 |
| 206401449 | ELIOS | DE24HOS25230E3A | DM24HIDU230X5 | -30 |
| 7086358 | FRIEDRICH | MRH12Y3J | MWH12Y3J | -25 |
| 5674834 | FUJITSU | AOU15RLS2H | ASU15RLS2 | -26 |

| | | | | |
|-----------|---------------|-------------------|--------------------|-----|
| 6937309 | FUJITSU | AOU9RLFFH | AGU9RLF | -26 |
| 6937310 | FUJITSU | AOU12RLFFH | AGU12RLF | -26 |
| 6937311 | FUJITSU | AOU15RLFFH | AGU15RLF | -26 |
| 7993244 | FUJITSU | AOU12RLS3H | ASU12RLS3 | -26 |
| 7993245 | FUJITSU | AOU15RLS3H | ASU15RLS3 | -26 |
| 8004700 | FUJITSU | AOU9RLS3H | ASU9RLS3 | -26 |
| 8703349 | FUJITSU | AOU9RLS3H | ASU9RLS3Y | -25 |
| 8703506 | FUJITSU | AOU12RLS3H | ASU12RLS3Y | -25 |
| 8703508 | FUJITSU | AOU15RLS3H | ASU15RLS3Y | -25 |
| 8779045 | FUJITSU | AOU18RLXFWH | ASU18RLF | -26 |
| 8779046 | FUJITSU | AOU24RLXFWH | ASU24RLF | -26 |
| 204740067 | FUJITSU | AOUG09LZAH1 | ASUG09LZAS | -26 |
| 204740069 | FUJITSU | AOUG12LZAH1 | ASUG12LZAS | -26 |
| 204740071 | FUJITSU | AOUG15LZAH1 | ASUG15LZAS | -26 |
| 206263449 | FUJITSU | AOUH09LMAH1 | ASUH09LMAS | -25 |
| 206263450 | FUJITSU | AOUH12LMAH1 | ASUH12LMAS | -25 |
| 206597209 | FUJITSU | AOUG09LZAH1 | ASUG09LZBS | -26 |
| 206597211 | FUJITSU | AOUG12LZAH1 | ASUG12LZBS | -26 |
| 206597213 | FUJITSU | AOUG15LZAH1 | ASUG15LZBS | -26 |
| 202588310 | GE Appliances | ASH109PRDWA | ASYW09PRDWB | -26 |
| 202588311 | GE Appliances | ASH112PRDWA | ASYW12PRDWB | -26 |
| 202588312 | GE Appliances | ASH115PRDWA | ASYW15PRDWB | -26 |
| 202588313 | GE Appliances | ASH118PRDWA | ASYW18PRDWB | -26 |
| 202588314 | GE Appliances | ASH124PRDWA | ASYW24PRDWB | -26 |
| 205291988 | GE Appliances | ASH109URDSD* | ASYW09URDWD* | -35 |
| 205291989 | GE Appliances | ASH112URDSD* | ASYW12URDWD* | -35 |
| 205291990 | GE Appliances | ASH118URDSD* | ASYW18URDWD* | -35 |
| 206842132 | GE Appliances | ASH118URDSE* | ASYW18URDWD* | -35 |
| 206842133 | GE Appliances | ASH112URDSE* | ASYW12URDWD* | -35 |
| 206842134 | GE Appliances | ASH118URDSE* | ASYW18URDWD* | -35 |
| 10062552 | GOODMAN | MSH183E21MCAA | MSH183E21AXAA | -26 |
| 10062553 | GOODMAN | MSH243E21MCAA | MSH243E21AXAA | -26 |
| 7070719 | GREE | GWH24QE-D3DNA1D/O | GWH24QE-D3DN***/I | -25 |
| 7091970 | GREE | GWH09QC-D3DNA1D/O | GWH09QC-D3DN***/I | -25 |
| 7091971 | GREE | GWH12QC-D3DNA1D/O | GWH12QC-D3DN***/I | -25 |
| 7201805 | GREE | GWH09UC-D3DNA4A/O | GWH09UC-D3DN***/I | -30 |
| 7201806 | GREE | GWH12UC-D3DNA4A/O | GWH12UC-D3DN***/I | -30 |
| 7201807 | GREE | GWH18UC-D3DNA4A/O | GWH18UC-D3DN***/I | -30 |
| 7607465 | GREE | GWH09UC-D3DNA4C/O | GWH09UC-D3DN***/I | -30 |
| 7607467 | GREE | GWH12UC-D3DNA4C/O | GWH12UC-D3DN***/I | -30 |
| 7607469 | GREE | GWH18UC-D3DNA4C/O | GWH18UC-D3DN***/I | -30 |
| 8000864 | GREE | GWH18QD-D3DNA1G/O | GWH18QD-D3DN***/I | -25 |
| 9114294 | GREE | GWH18YE-D3DNA1A/O | GWH18AAE-D3DN***/I | -30 |
| 9123256 | GREE | GWH24YE-D3DNA1A/O | GWH24AAE-D3DN***/I | -30 |
| 9944775 | GREE | GWH09YD-D3DNA1A/O | GWH09AAD-D3DN***/I | -30 |
| 9944776 | GREE | GWH12YD-D3DNA1A/O | GWH12AAD-D3DN***/I | -30 |
| 10146838 | GREE | GWH15QD-D3DNA5G/O | GWH15QD-D3DN***/I | -25 |

| | | | | |
|-----------|---------|--------------------|--------------------|-----|
| 10149900 | GREE | SAP09HP230V1AO | SAP09HP230V1AH | -30 |
| 9116197 | GREE | GWH12YD-D3DNA1A/O | GWH12QD-D3DN***/I | -30 |
| 10149903 | GREE | SAP12HP230V1AO | SAP12HP230V1AH | -30 |
| 10157570 | GREE | SAP18HP230V1AO | SAP18HP230V1AH | -30 |
| 10157571 | GREE | SAP24HP230V1AO | SAP24HP230V1AH | -30 |
| 204325176 | GREE | GWH09ACD-D3DNA1A/O | GWH09AAD-D3DN***/I | -30 |
| 9102074 | GREE | GWH18YE-D3DNA1A/O | GWH18QE-D3DN***/I | -30 |
| 8862047 | HAIER | 1U09EH2VHA | AW09EH2VHA | -26 |
| 8862052 | HAIER | 1U12EH2VHA | AW12EH2VHA | -26 |
| 8862057 | HAIER | 1U18EH2VHA | AW18EH2VHA | -26 |
| 202583709 | HAIER | 1U09AP2VHA | AW09ES2VHB | -26 |
| 202583710 | HAIER | 1U18AP2VHA | AW18ES2VHB | -26 |
| 202583711 | HAIER | 1U12AP2VHA | AW12ES2VHB | -26 |
| 202583712 | HAIER | 1U15AP2VHA | AW15ES2VHB | -26 |
| 202583713 | HAIER | 1U24AP2VHA | AW24ES2VHB | -26 |
| 205291901 | HAIER | 1U09EH2VHD* | AW09EH2VHD* | -35 |
| 205291902 | HAIER | 1U12EH2VHD* | AW12EH2VHD* | -35 |
| 205291903 | HAIER | 1U18EH2VHD* | AW18EH2VHD* | -35 |
| 206608650 | HAIER | 1U09EH2VHE* | USYM09UCDSA* | -35 |
| 206389355 | HAIER | 1U12EH2VHE* | USYF12UCDWA* | -35 |
| 206389356 | HAIER | 1U12EH2VHE* | AB12SC2VHA* | -35 |
| 206389354 | HAIER | 1U12EH2VHE* | USYM12UCDSA* | -35 |
| 206445819 | HAIER | 1U09EH2VHE* | AW09EH2VHD* | -35 |
| 206389351 | HAIER | 1U12EH2VHE* | AW12EH2VHD* | -35 |
| 206445820 | HAIER | 1U18EH2VHE* | AW18EH2VHD* | -35 |
| 8177081 | HEIL | DLCAHB09K1A | DLFAHH09K1A | -30 |
| 8177090 | HEIL | DLCAHB12K1A | DLFAHH12K1A | -30 |
| 8177099 | HEIL | DLCAHB18K1A | DLFAHH18K1A | -30 |
| 201835653 | HEIL | DLCPRAH09AAK | DLFPHAH09XAK | -25 |
| 201835654 | HEIL | DLCPRAH12AAK | DLFPHAH12XAK | -25 |
| 201835667 | HEIL | DLCSRAH09AAJ | DLFSHAH09XAJ | -25 |
| 201835668 | HEIL | DLCSRAH12AAJ | DLFSHAH12XAJ | -25 |
| 201835670 | HEIL | DLCSRAH09AAK | DLFSHAH09XAK | -25 |
| 201835672 | HEIL | DLCSRAH12AAK | DLFSHAH12XAK | -25 |
| 201835674 | HEIL | DLCSRAH18AAK | DLFSHAH18XAK | -25 |
| 201835676 | HEIL | DLCSRAH24AAK | DLFSHAH24XAK | -25 |
| 201835704 | HEIL | DLCSRAH09AAK | DLFSDAH09XAK | -25 |
| 201835706 | HEIL | DLCSRAH09AAK | DLFSCAH09XAK | -25 |
| 201835708 | HEIL | DLCSRAH12AAK | DLFSCAH12XAK | -25 |
| 201835710 | HEIL | DLCSRAH12AAK | DLFSFAH12XAK | -25 |
| 201835712 | HEIL | DLCSRAH12AAK | DLFSDAH12XAK | -25 |
| 201835714 | HEIL | DLCSRAH18AAK | DLFSFAH18XAK | -25 |
| 201835716 | HEIL | DLCSRAH18AAK | DLFSCAH18XAK | -25 |
| 201835718 | HEIL | DLCSRAH24AAK | DLFSDAH24XAK | -25 |
| 201835728 | HEIL | DLCSRAH18AAK | DLFSDAH18XAK | -25 |
| 201981253 | HISENSE | AS-09UW3SXE** | AS-09UW3SXE** | -25 |
| 201981254 | HISENSE | AS-12UW3SXA** | AS-12UW3SXA** | -25 |

| | | | | |
|-----------|----------|--------------------|--------------------|-----|
| 201830345 | KARDA | 1PAMSHH09-SZO-25 | 1PAMSHH09-SZW-25 | -25 |
| 201830346 | KARDA | 1PAMSHH12-SZO-22.5 | 1PAMSHH12-SZW-22.5 | -25 |
| 201830347 | KARDA | 1PAMSHH18-SZO-22.5 | 1PAMSHH18-SZW-22.5 | -25 |
| 201830348 | KARDA | 1PAMSHH24-SZO-20.5 | 1PAMSHH24-SZW-20.5 | -25 |
| 202140576 | KARDA | 2PAMSHH18-SZO-20 | 2PAMSHH18-SZW-20 | -30 |
| 205756426 | KARDA | 1KARDA09SZO25 | 1KARDA09UVW | -30 |
| 205756427 | KARDA | 1KARDA12SZO22.5 | 1KARDA12UVW | -30 |
| 205756428 | KARDA | 2KARDA18SZO20 | 2KARDA18UVW | -30 |
| 205756430 | KARDA | 1PAMSHH09-SZO-25 | 1KARDA09UVW | -30 |
| 205756431 | KARDA | 1PAMSHH12-SZO-22.5 | 1KARDA12UVW | -30 |
| 205756432 | KARDA | 2PAMSHH18-SZO-20 | 2KARDA18UVW | -30 |
| 205756433 | KARDA | 1PAMSHH24-SZO-20.5 | 2KARDA24UVW | -30 |
| 206900448 | KARDA | 1KARDA12SZO22.5 | 2PAMSCONH12 | -30 |
| 8177082 | KEEPRITE | DLCAHB09K1A | DLFAHH09K1A | -30 |
| 8177091 | KEEPRITE | DLCAHB12K1A | DLFAHH12K1A | -30 |
| 8177100 | KEEPRITE | DLCAHB18K1A | DLFAHH18K1A | -30 |
| 201835652 | KEEPRITE | DLCBRAH09AAK | DLFPHAH09XAK | -25 |
| 201835655 | KEEPRITE | DLCBRAH12AAK | DLFPHAH12XAK | -25 |
| 201835666 | KEEPRITE | DLCSRAH09AAJ | DLFSHAH09XAJ | -25 |
| 201835669 | KEEPRITE | DLCSRAH12AAJ | DLFSHAH12XAJ | -25 |
| 201835671 | KEEPRITE | DLCSRAH09AAK | DLFSHAH09XAK | -25 |
| 201835673 | KEEPRITE | DLCSRAH12AAK | DLFSHAH12XAK | -25 |
| 201835675 | KEEPRITE | DLCSRAH18AAK | DLFSHAH18XAK | -25 |
| 201835677 | KEEPRITE | DLCSRAH24AAK | DLFSHAH24XAK | -25 |
| 201835705 | KEEPRITE | DLCSRAH09AAK | DLFSDAH09XAK | -25 |
| 201835707 | KEEPRITE | DLCSRAH09AAK | DLFSCAH09XAK | -25 |
| 201835709 | KEEPRITE | DLCSRAH12AAK | DLFSCAH12XAK | -25 |
| 201835711 | KEEPRITE | DLCSRAH12AAK | DLFSFAH12XAK | -25 |
| 201835713 | KEEPRITE | DLCSRAH12AAK | DLFSDAH12XAK | -25 |
| 201835715 | KEEPRITE | DLCSRAH18AAK | DLFSFAH18XAK | -25 |
| 201835717 | KEEPRITE | DLCSRAH18AAK | DLFSCAH18XAK | -25 |
| 201835719 | KEEPRITE | DLCSRAH24AAK | DLFSDAH24XAK | -25 |
| 201835729 | KEEPRITE | DLCSRAH18AAK | DLFSDAH18XAK | -25 |
| 206361890 | KEEPRITE | DLCSRBH12AAK | DLFSHBH12XAK | -30 |
| 206361892 | KEEPRITE | DLCSRBH24AAK | DLFSHBH24XAK | -30 |
| 206361889 | KEEPRITE | DLCSRBH09AAK | DLFSHBH09XAK | -30 |
| 206361891 | KEEPRITE | DLCSRBH18AAK | DLFSHBH18XAK | -30 |
| 205767352 | KEEPRITE | DLCLRBH36AAK | DLFLAAH36XAK | -30 |
| 206350431 | KEEPRITE | DLCSRBH18AAK | DLFSCAH18XAK | -30 |
| 206350428 | KEEPRITE | DLCSRBH12AAK | DLFSCAH12XAK | -30 |
| 8177086 | KENMORE | DLCAHB09K1A | DLFAHH09K1A | -30 |
| 8177095 | KENMORE | DLCAHB12K1A | DLFAHH12K1A | -30 |
| 8177104 | KENMORE | DLCAHB18K1A | DLFAHH18K1A | -30 |
| 201835749 | KENMORE | DLCBRAH09AAK | DLFPHAH09XAK | -25 |
| 201835751 | KENMORE | DLCBRAH12AAK | DLFPHAH12XAK | -25 |
| 201835762 | KENMORE | DLCSRAH09AAJ | DLFSHAH09XAJ | -25 |
| 201835764 | KENMORE | DLCSRAH12AAJ | DLFSHAH12XAJ | -25 |

| | | | | |
|-----------|----------|--------------------|--------------------|-----|
| 201835766 | KENMORE | DLCSRAH09AAK | DLFSHAH09XAK | -25 |
| 201835768 | KENMORE | DLCSRAH12AAK | DLFSHAH12XAK | -25 |
| 201835770 | KENMORE | DLCSRAH18AAK | DLFSHAH18XAK | -25 |
| 201835772 | KENMORE | DLCSRAH24AAK | DLFSHAH24XAK | -25 |
| 201835801 | KENMORE | DLCSRAH09AAK | DLFSDAH09XAK | -25 |
| 201835803 | KENMORE | DLCSRAH09AAK | DLFSCAH09XAK | -25 |
| 201835805 | KENMORE | DLCSRAH12AAK | DLFSCAH12XAK | -25 |
| 201835807 | KENMORE | DLCSRAH12AAK | DLFSFAH12XAK | -25 |
| 201835809 | KENMORE | DLCSRAH12AAK | DLFSDAH12XAK | -25 |
| 201835811 | KENMORE | DLCSRAH18AAK | DLFSFAH18XAK | -25 |
| 201835813 | KENMORE | DLCSRAH18AAK | DLFSCAH18XAK | -25 |
| 201835815 | KENMORE | DLCSRAH24AAK | DLFSDAH24XAK | -25 |
| 201835825 | KENMORE | DLCSRAH18AAK | DLFSDAH18XAK | -25 |
| 9710789 | KERR | A-KMH09SU-1 | B-KMH09SU-1 | -30 |
| 9710790 | KERR | A-KMH12SU-1 | B-KMH12SU-1 | -30 |
| 9710791 | KERR | A-KMH24SU-1 | B-KMH24SU-1 | -30 |
| 9989564 | KERR | A-KMH18SU-1 | B-KMH18SU-1 | -30 |
| 201866485 | KERR | A-KMH18SU-1A | B-KMH18SU-1A | -30 |
| 205747697 | KERR | A-KMH18SU-1A | B-KMH18SU-1A | -30 |
| 206221393 | KERR | A-KMH24SU-1A | B-KMH24SU-1A | -30 |
| 202110998 | KERR | A-KMH12SU-1 | B-KMH12DU-1 | -30 |
| 207657393 | KERR | A-KMH06SV-1 | B-KMH06SV-1 | -30 |
| 207657394 | KERR | A-KMH09SV-1 | B-KMH09SV-1 | -30 |
| 207657395 | KERR | A-KMH12SV-1 | B-KMH12SV-1 | -30 |
| 207657396 | KERR | A-KMH18SV-1 | B-KMH18SV-1 | -30 |
| 207657397 | KERR | A-KMH24SV-1 | B-KMH24SV-1 | -30 |
| 203493069 | KINGHOME | KW09HQ3D6DO | KW09HQ3D6DI | -30 |
| 203493070 | KINGHOME | KW12HQ3D6DO | KW12HQ3D6DI | -30 |
| 203493071 | KINGHOME | KW18HQ3D6DO | KW18HQ3D6DI | -30 |
| 203498481 | KINGHOME | KW24HQ3D6DO | KW24HQ3D6DI | -30 |
| 10333036 | KINGHOME | KW09HQ2B8DO | KW09HQ2B8DI | -25 |
| 10333037 | KINGHOME | KW12HQ2B8DO | KW12HQ2B8DI | -25 |
| 10333040 | KINGHOME | KW18HQ2B8DO | KW18HQ2B8DI | -25 |
| 10338140 | KINGHOME | KW24HQ2B8DO | KW24HQ2B8DI | -25 |
| 8849281 | KOOLKING | MOB30-12HFN1-MVOW | CS11M-12HRFN1-MU5W | -30 |
| 8849282 | KOOLKING | MOCA30-18HFN1-MTOW | CS11M-18HRFN1-MTOW | -30 |
| 8849283 | KOOLKING | MOD30-24HFN1-MTOW | CS11M-23HRFN1-MTOW | -30 |
| 200059043 | KOOLKING | MOCA30-18HFN1-MTOW | CS11M-18HRFN1-MTOW | -25 |
| 200059046 | KOOLKING | MOD30-24HFN1-MTOW | CS11M-23HRFN1-MTOW | -25 |
| 8129512 | LENNOX | MPA009S4S-1L | MWMA009S4-1L | -25 |
| 8129519 | LENNOX | MPA012S4S-1L | MWMA012S4-1L | -25 |
| 8129529 | LENNOX | MPA009S4S-1P | MWMA009S4-1P | -25 |
| 8129532 | LENNOX | MPA012S4S-1P | MWMA012S4-1P | -25 |
| 8129542 | LENNOX | MPA024S4S-1P | MWMA024S4-1P | -25 |
| 8129557 | LENNOX | MPA009S4S-1P | M22A009S4-1P | -25 |
| 8129566 | LENNOX | MPA012S4S-1P | M22A012S4-1P | -25 |
| 8232197 | LENNOX | MPA012S4S-1P | MCF012S4-1P | -25 |

| | | | | |
|-----------|--------|--------------|--------------|-----|
| 9920041 | LENNOX | MLA012S4S-1P | MWMA012S4-2P | -25 |
| 9920044 | LENNOX | MLA018S4S-1P | MWMA018S4-2P | -30 |
| 9920047 | LENNOX | MLA024S4S-1P | MWMA024S4-2P | -30 |
| 9956319 | LENNOX | MLA018S4S-1P | MCFB018S4-2P | -30 |
| 9962874 | LENNOX | MPA012S4S-1P | MWMA012S4-2P | -25 |
| 9962879 | LENNOX | MPA012S4S-1P | MMDA012S4-2P | -25 |
| 9962880 | LENNOX | MPA012S4S-1P | M22A012S4-2P | -25 |
| 10056167 | LENNOX | MPB009S4S-1L | MWMB009S4-1L | -25 |
| 10056168 | LENNOX | MPB012S4S-1L | MWMB012S4-1L | -25 |
| 10056169 | LENNOX | MPB009S4S-1P | MWMA009S4-1P | -25 |
| 10056170 | LENNOX | MPB009S4S-1P | MWMA009S4-2P | -25 |
| 10056171 | LENNOX | MPB012S4S-1P | MWMA012S4-1P | -25 |
| 10056172 | LENNOX | MPB012S4S-1P | MWMA012S4-2P | -25 |
| 10056173 | LENNOX | MPB018S4S-1P | MWMA018S4-1P | -25 |
| 10056174 | LENNOX | MPB018S4S-1P | MWMA018S4-2P | -25 |
| 10056175 | LENNOX | MPB024S4S-1P | MWMA024S4-1P | -25 |
| 10056176 | LENNOX | MPB024S4S-1P | MWMA024S4-2P | -25 |
| 10058825 | LENNOX | MPB018S4S-1P | MCFB018S4-2P | -25 |
| 10058826 | LENNOX | MPB024S4S-1P | MCFA024S4-1P | -25 |
| 10058827 | LENNOX | MPB024S4S-1P | MCFA024S4-2P | -25 |
| 10058830 | LENNOX | MPB009S4S-1P | M22A009S4-1P | -25 |
| 10058831 | LENNOX | MPB009S4S-1P | M22A009S4-2P | -25 |
| 10058832 | LENNOX | MPB012S4S-1P | M22A012S4-1P | -25 |
| 10058834 | LENNOX | MPB018S4S-1P | M22A018S4-1P | -25 |
| 10058835 | LENNOX | MPB018S4S-1P | M22A018S4-2P | -25 |
| 10058836 | LENNOX | MPB024S4S-1P | M33A024S4-1P | -25 |
| 10058837 | LENNOX | MPB024S4S-1P | M33A024S4-2P | -25 |
| 201796628 | LENNOX | MPB009S4S-1L | MWMB009S4-2L | -25 |
| 201796629 | LENNOX | MPB012S4S-1L | MWMB012S4-2L | -25 |
| 201796630 | LENNOX | MPB009S4S-1P | MWMA009S4-3P | -25 |
| 201796631 | LENNOX | MPB012S4S-1P | MWMA012S4-3P | -25 |
| 201796632 | LENNOX | MLA009S4S-1P | MWMA009S4-3P | -30 |
| 201796633 | LENNOX | MLA012S4S-1P | MWMA012S4-3P | -30 |
| 205747587 | LENNOX | MLA012S4S-1P | MFMA012S4-1P | -30 |
| 6233140 | LG | LAU120HYV | LAN120HYV | -25 |
| 6236101 | LG | LSU240HSV3 | LSN240HSV3 | -25 |
| 6468419 | LG | LAU090HYV | LAN090HYV | -25 |
| 7484109 | LG | LSU090HSV4 | LAN090HSV4 | -25 |
| 7484110 | LG | LSU090HSV4 | LSN090HSV4 | -25 |
| 7484111 | LG | LSU120HSV4 | LAN120HSV4 | -25 |
| 7484112 | LG | LSU120HSV4 | LSN120HSV4 | -25 |
| 7845625 | LG | LGU121HSV2 | LGN121HSV2 | -25 |
| 7849625 | LG | LAU120HYV1 | LAN120HYV1 | -25 |
| 7947563 | LG | LAU090HYV1 | LAN090HYV1 | -25 |
| 8584525 | LG | LAU180HYV1 | LAN180HYV1 | -25 |
| 8584526 | LG | LAU240HYV1 | LAN240HYV1 | -25 |
| 9680935 | LG | LAU150HYV2 | LAN150HYV2 | -25 |

| | | | | |
|-----------|-------|--------------------|--------------------|-----|
| 10567390 | LG | LSU180HSV5 | LAN180HSV5 | -25 |
| 10567391 | LG | LSU180HSV5 | LSN180HSV5 | -25 |
| 10567392 | LG | LGU181HSV3 | LGN181HSV3 | -25 |
| 10567393 | LG | LSU090HSV5 | LAN090HSV5 | -25 |
| 10567394 | LG | LSU090HSV5 | LSN090HSV5 | -25 |
| 10570122 | LG | LSU120HSV5 | LAN120HSV5 | -25 |
| 10570123 | LG | LSU120HSV5 | LSN120HSV5 | -25 |
| 10570124 | LG | LGU121HSV3 | LGN121HSV3 | -25 |
| 204825177 | LG | LAU090HYV3 | LAN090HYV3 | -25 |
| 204825178 | LG | LAU120HYV3 | LAN120HYV3 | -25 |
| 204825179 | LG | LAU150HYV3 | LAN150HYV3 | -25 |
| 204825180 | LG | LAU180HYV3 | LAN180HYV3 | -25 |
| 204825181 | LG | LAU240HYV3 | LAN240HYV3 | -25 |
| 205788763 | LG | LUU180HHV | LCN188HV4 | -25 |
| 205788767 | LG | LUU240HHV | LHN248HV | -25 |
| 205788769 | LG | LUU360HHV | LHN368HV | -25 |
| 205788770 | LG | LUU420HHV | LHN428HV | -25 |
| 205788772 | LG | LUU480HHV | LHN488HV | -25 |
| 205788764 | LG | LUU240HHV | LCN249HV | -25 |
| 205788768 | LG | LUU360HHV | LCN369HV | -25 |
| 205788765 | LG | LUU420HHV | LCN429HV | -25 |
| 205788766 | LG | LUU180HHV | LDN187HV4 | -25 |
| 8779181 | MDV | MOBA01-09HFN1-BTOW | MSMBB-09HRFN1-BTOW | -25 |
| 8740667 | MDV | MOBA30-09HFN1-MTOW | CCA3U-09HRFN1-M(C) | -25 |
| 7000012 | MIDEA | MOZ-09HFN1-MX4W | MS11M-09HRFN1-MX4W | -25 |
| 7000013 | MIDEA | MOZ-12HFN1-MW0W | MS11M-12HRFN1-MW0W | -25 |
| 8779199 | MIDEA | MCHS-09PSH1 | MEHS-09PSH1 | -25 |
| 8779200 | MIDEA | MCHS-12PSH1 | MEHS-12PSH1 | -30 |
| 8779201 | MIDEA | MCHSU-09PHH2 | MEHSU-09PHH2 | -30 |
| 8779202 | MIDEA | MCHSU-12PHH2 | MEHSU-12PHH2 | -30 |
| 8779203 | MIDEA | MCHSU-18PHH2 | MEHSU-18PHH2 | -30 |
| 8779204 | MIDEA | MCHSU-24PHH2 | MEHSU-24PHH2 | -30 |
| 200059044 | MIDEA | MOCA30-18HFN1-MTOW | CS11M-18HRFN1-MTOW | -25 |
| 200059047 | MIDEA | MOD30-24HFN1-MTOW | CS11M-23HRFN1-MTOW | -25 |
| 201753970 | MIDEA | 38MPRAQ09AA3 | DHMPHAQ09XA3 | -25 |
| 201753971 | MIDEA | 38MPRAQ12AA3 | DHMPHAQ12XA3 | -25 |
| 201753972 | MIDEA | DLCPRAH09AAK | DLFPHAH09XAK | -25 |
| 201755033 | MIDEA | DLCPRAH12AAK | DLFPHAH12XAK | -25 |
| 201756545 | MIDEA | DLCSRAH09AAJ | DLFSHAH09XAJ | -25 |
| 201756546 | MIDEA | DLCSRAH12AAJ | DLFSHAH12XAJ | -25 |
| 201756547 | MIDEA | DLCSRAH09AAK | DLFSHAH09XAK | -25 |
| 201756548 | MIDEA | DLCSRAH12AAK | DLFSHAH12XAK | -25 |
| 201756549 | MIDEA | DLCSRAH18AAK | DLFSHAH18XAK | -25 |
| 201756550 | MIDEA | DLCSRAH24AAK | DLFSHAH24XAK | -25 |
| 201796605 | MIDEA | DLCSRAH09AAK | DLFSDAH09XAK | -25 |
| 201796606 | MIDEA | DLCSRAH09AAK | DLFSCAH09XAK | -25 |
| 201796607 | MIDEA | DLCSRAH12AAK | DLFSCAH12XAK | -25 |

| | | | | |
|-----------|------------|--------------|--------------|-----|
| 201796608 | MIDEA | DLCSRAH12AAK | DLFSFAH12XAK | -25 |
| 201796609 | MIDEA | DLCSRAH12AAK | DLFSDAH12XAK | -25 |
| 201796610 | MIDEA | DLCSRAH18AAK | DLFSFAH18XAK | -25 |
| 201796611 | MIDEA | DLCSRAH18AAK | DLFSCAH18XAK | -25 |
| 201796612 | MIDEA | DLCSRAH24AAK | DLFSDAH24XAK | -25 |
| 201796617 | MIDEA | DLCSRAH18AAK | DLFSDAH18XAK | -25 |
| 201846986 | MIDEA | 38MAQB09R--1 | DHMSHAQ09XA1 | -25 |
| 201846987 | MIDEA | 38MAQB12R--1 | DHMSHAQ12XA1 | -25 |
| 201846988 | MIDEA | 38MAQB09R--3 | DHMSHAQ09XA3 | -25 |
| 201846989 | MIDEA | 38MAQB12R--3 | DHMSHAQ12XA3 | -25 |
| 201846990 | MIDEA | 38MAQB18R--3 | DHMSHAQ18XA3 | -25 |
| 201846991 | MIDEA | 38MAQB24R--3 | DHMSHAQ24XA3 | -25 |
| 201846992 | MIDEA | 38MAQB09R--3 | 40MBCQ09---3 | -25 |
| 201846993 | MIDEA | 38MAQB12R--3 | 40MBCQ12---3 | -25 |
| 201846994 | MIDEA | 38MAQB18R--3 | 40MBCQ18---3 | -25 |
| 201846995 | MIDEA | 38MAQB09R--3 | 40MBDQ09---3 | -25 |
| 201846996 | MIDEA | 38MAQB12R--3 | 40MBDQ12---3 | -25 |
| 201846997 | MIDEA | 38MAQB18R--3 | 40MBDQ18---3 | -25 |
| 201846998 | MIDEA | 38MAQB24R--3 | 40MBDQ24---3 | -25 |
| 201846999 | MIDEA | 38MAQB12R--3 | 40MBFQ12---3 | -25 |
| 201847000 | MIDEA | 38MAQB18R--3 | 40MBFQ18---3 | -25 |
| 206188281 | MIDEA | 38MARBQ24AA3 | 40MBAAQ24XA3 | -30 |
| 206350380 | MIDEA | 38MARBQ24AA3 | 40MBDQ24---3 | -30 |
| 206350320 | MIDEA | 38MARBQ18AA3 | DHMAHBQ18XA3 | -30 |
| 206350376 | MIDEA | 38MARBQ18AA3 | 40MBCQ18---3 | -30 |
| 206350377 | MIDEA | 38MARBQ18AA3 | 40MBDQ18---3 | -30 |
| 206350378 | MIDEA | 38MARBQ18AA3 | 40MBFQ18---3 | -30 |
| 206400662 | MIDEA | 38MARBQ18AA3 | DHMSHAQ18XA3 | -30 |
| 206350373 | MIDEA | 38MARBQ12AA3 | 40MBCQ12---3 | -30 |
| 4217888 | mitsubishi | MUZ-FE18NA | MSZ-FE18NA | -25 |
| 4908219 | mitsubishi | MUZ-FE09NA-1 | MSZ-FE09NA | -25 |
| 4934170 | mitsubishi | MUZ-FE12NA1 | MSZ-FE12NA | -25 |
| 5377911 | mitsubishi | MUZ-FE09NAH | MSZ-FE09NA | -25 |
| 5378525 | mitsubishi | MUZ-FE12NAH | MSZ-FE12NA | -25 |
| 7002062 | mitsubishi | MUZ-FH09NA | MSZ-FH09NA | -25 |
| 7002063 | mitsubishi | MUZ-FH12NA | MSZ-FH12NA | -25 |
| 7002444 | mitsubishi | MUZ-FH15NA | MSZ-FH15NA | -25 |
| 7002504 | mitsubishi | MUZ-FH09NAH | MSZ-FH09NA | -25 |
| 7002578 | mitsubishi | MUZ-FH12NAH | MSZ-FH12NA | -25 |
| 7002594 | mitsubishi | MUZ-FH15NAH | MSZ-FH15NA | -25 |
| 8107718 | mitsubishi | MUZ-FH18NAH | MSZ-FH18NA | -25 |
| 8111727 | mitsubishi | MUZ-FH18NA | MSZ-FH18NA | -25 |
| 8703451 | mitsubishi | MUZ-FH12NAH | MSZ-FH12NA** | -25 |
| 8737963 | mitsubishi | MUZ-FH09NAH | MSZ-FH09NA** | -25 |
| 8737964 | mitsubishi | MUZ-FH15NAH | MSZ-FH15NA** | -25 |
| 8737965 | mitsubishi | MUZ-GE09NAH | MSZ-GE09NA** | -25 |

| | | | | |
|-----------|----------------------|----------------|----------------|-----|
| 8737966 | mitsubishi | MUZ-GE12NAH | MSZ-GE12NA** | -25 |
| 8737967 | mitsubishi | MUZ-GE15NAH | MSZ-GE15NA** | -25 |
| 8737968 | mitsubishi | MUZ-FE09NAH | MSZ-FE09NA** | -25 |
| 8737969 | mitsubishi | MUZ-FE12NAH | MSZ-FE12NA** | -25 |
| 201754291 | mitsubishi | MUFZ-KJ12NAHZ | MFZ-KJ12NA | -25 |
| 201754293 | mitsubishi | MUFZ-KJ18NAHZ | MFZ-KJ18NA | -25 |
| 201754295 | mitsubishi | MUZ-FE12NAH | MSZ-FE12NA** | -25 |
| 201754296 | mitsubishi | MUZ-FH09NA | MSZ-FH09NA | -25 |
| 201754297 | mitsubishi | MUZ-FH09NAH | MSZ-FH09NA** | -25 |
| 201754298 | mitsubishi | MUZ-FH12NA | MSZ-FH12NA | -25 |
| 201754299 | mitsubishi | MUZ-FH12NAH | MSZ-FH12NA** | -25 |
| 201754300 | mitsubishi | MUZ-FH15NA | MSZ-FH15NA | -25 |
| 201754301 | mitsubishi | MUZ-FH15NAH | MSZ-FH15NA** | -25 |
| 201754302 | mitsubishi | MUZ-FH18NA2 | MSZ-FH18NA** | -25 |
| 201754303 | mitsubishi | MUZ-FH18NAH2 | MSZ-FH18NA** | -25 |
| 201754305 | mitsubishi | MUZ-GE12NAH2 | MSZ-GE12NA | -25 |
| 201754425 | mitsubishi | MUZ-FE09NAH | MSZ-FE09NA** | -25 |
| 201754427 | mitsubishi | MUZ-FH06NAH | MSZ-FH06NA** | -25 |
| 201754646 | mitsubishi | MUZ-GE09NAH2 | MSZ-GE09NA | -25 |
| 201754416 | mitsubishi | MUFZ-KJ09NAHZ | MFZ-KJ09NA | -25 |
| 205975736 | Mitsubishi Electric | MUZ-FS06NAH-U1 | MSZ-FS06NA-U1 | -25 |
| 205975737 | Mitsubishi Electric | MUZ-FS09NAH-U1 | MSZ-FS09NA-U1 | -25 |
| 205975738 | Mitsubishi Electric | MUZ-FS12NAH-U1 | MSZ-FS12NA-U1 | -25 |
| 205975739 | Mitsubishi Electric | MUZ-FS15NAH-U1 | MSZ-FS15NA-U1 | -25 |
| 205975740 | Mitsubishi Electric | MUZ-FS18NAH-U1 | MSZ-FS18NA-U1 | -25 |
| 204276538 | Mitsubishi Electric | PUZ-HA24NHA | PLA-A24EA7 | -25 |
| 204276761 | Mitsubishi Electric | PUZ-HA24NHA | PKA-A24KA7 | -25 |
| 204276762 | Mitsubishi Electric | PUZ-HA24NHA | PCA-A24KA7 | -25 |
| 206223093 | Mitsubishi Electric | PUZ-HA36NKA | PLA-A36EA7 | -25 |
| 206223042 | Mitsubishi Electric | PUZ-HA24NHA1 | PCA-A24KA7 | -25 |
| 206223041 | Mitsubishi Electric | PUZ-HA24NHA1 | PKA-A24KA7 | -25 |
| 206223004 | Mitsubishi Electric | PUZ-HA24NHA1 | PLA-A24EA7 | -25 |
| 206223055 | Mitsubishi Electric | PUZ-HA36NKA | PCA-A36KA7 | -25 |
| 201754292 | Mitsubishi Electric | MUFZ-KJ15NAHZ | MFZ-KJ15NA | -25 |
| 202102474 | mitsubishi; AMERICAN | MUZ-FH18NAH2 | MSZ-FH18NA** | -25 |
| 203238509 | MOOVAIR | DM09HOS23230E2 | DM09HIW23230E3 | -25 |
| 203238510 | MOOVAIR | DM12HOS23230E2 | DM12HIW23230E3 | -25 |
| 203238512 | MOOVAIR | DM18HOS23230E2 | DM18HIW23230E3 | -25 |
| 203238514 | MOOVAIR | DM24HOS23230E2 | DM24HIW23230E3 | -25 |
| 204005732 | MOOVAIR | DM09HOS25230E3 | DM09HIW23230E3 | -30 |
| 204005733 | MOOVAIR | DM12HOS25230E3 | DM12HIW23230E3 | -30 |
| 204005734 | MOOVAIR | DM18HOS25230E3 | DM18HIW23230E3 | -30 |
| 204005735 | MOOVAIR | DM24HOS25230E3 | DM24HIW23230E3 | -30 |
| 204005736 | MOOVAIR | DM09HOS23230E2 | DM09HIDU230X5 | -25 |
| 204005737 | MOOVAIR | DM12HOS23230E2 | DM12HIDU230X5 | -25 |
| 204005738 | MOOVAIR | DM18HOS23230E2 | DM18HIDU230X5 | -25 |

| | | | | |
|-----------|-------------|------------------|-------------------|-----|
| 204005739 | MOOVAIR | DM24HOS23230E2 | DM24HIDU230X5 | -25 |
| 204005740 | MOOVAIR | DM09HOS25230E3 | DM09HIDU230X5 | -30 |
| 204005741 | MOOVAIR | DM12HOS25230E3 | DM12HIDU230X5 | -30 |
| 204005742 | MOOVAIR | DM18HOS25230E3 | DM18HIDU230X5 | -30 |
| 204005743 | MOOVAIR | DM24HOS25230E3 | DM24HIDU230X5 | -30 |
| 204005744 | MOOVAIR | DM09HOS23230E2 | DM09HICU230X5 | -25 |
| 204005745 | MOOVAIR | DM12HOS23230E2 | DM12HICU230X5 | -25 |
| 204005746 | MOOVAIR | DM18HOS23230E2 | DM18HICU230X5 | -25 |
| 204005747 | MOOVAIR | DM24HOS23230E2 | DM24HICU230X5 | -25 |
| 204005748 | MOOVAIR | DM09HOS25230E3 | DM09HICU230X5 | -30 |
| 204005749 | MOOVAIR | DM12HOS25230E3 | DM12HICU230X5 | -30 |
| 204005750 | MOOVAIR | DM18HOS25230E3 | DM18HICU230X5 | -30 |
| 204005756 | MOOVAIR | DM24HOS25230E3 | DM24HICU230X5 | -30 |
| 205782168 | MOOVAIR | DM12HOS23230E2 | DM12HIFU230E5 | -25 |
| 205782167 | MOOVAIR | DM12HOS25230E3 | DM12HIFU230E5 | -25 |
| 206401439 | MOOVAIR | DM18HOS25230E3A | DM18HIW23230E3 | -30 |
| 206377754 | MOOVAIR | DM09HOS42230E4 | DM09HIW42230E4 | -30 |
| 206377756 | MOOVAIR | DM12HOS42230E4 | DM12HIW42230E4 | -30 |
| 206401440 | MOOVAIR | DM18HOS25230E3A | DM18HIDU230X5 | -30 |
| 206401441 | MOOVAIR | DM18HOS25230E3A | DM18HICU230X5 | -30 |
| 206401442 | MOOVAIR | DM24HOS25230E3A | DM24HIW23230E3 | -30 |
| 206401443 | MOOVAIR | DM24HOS25230E3A | DM24HIDU230X5 | -30 |
| 204783911 | MRCOOL | O-ES-09-HP-C-230 | O-09-HP-WMAH-230A | -25 |
| 204783912 | MRCOOL | O-ES-12-HP-C-230 | O-12-HP-WMAH-230A | -25 |
| 204783913 | MRCOOL | O-ES-18-HP-C-230 | O-18-HP-WMAH-230A | -25 |
| 204783914 | MRCOOL | O-ES-24-HP-C-230 | O-24-HP-WMAH-230A | -25 |
| 204783915 | MRCOOL | O-HH-09-HP-C-230 | O-09-HP-WMAH-230A | -30 |
| 204783916 | MRCOOL | O-HH-12-HP-C-230 | O-12-HP-WMAH-230A | -30 |
| 204783917 | MRCOOL | O-HH-18-HP-C-230 | O-18-HP-WMAH-230A | -30 |
| 204783918 | MRCOOL | O-HH-24-HP-C-230 | O-24-HP-WMAH-230A | -30 |
| 7072756 | NAPOLEON | NH23-09F-O | NH23-09F-I | -25 |
| 7072757 | NAPOLEON | NH23-12F-O | NH23-12F-I | -25 |
| 8952855 | NAPOLEON | NH25-09F-O | NH25-09F-I | -25 |
| 8952856 | NAPOLEON | NH25-12F-O | NH25-12F-I | -25 |
| 8952857 | NAPOLEON | NH25-18F-O | NH25-18F-I | -25 |
| 8952858 | NAPOLEON | NH25-24F-O | NH25-24F-I | -25 |
| 201786765 | NOVAIR PLUS | 09EVONVO | 09EVONVI | -25 |
| 201786767 | NOVAIR PLUS | 12EVONVO | 12EVONVI | -25 |
| 201786769 | NOVAIR PLUS | 18EVONVO | 18EVONVI | -25 |
| 201786770 | NOVAIR PLUS | 24EVONVO | 24EVONVI | -25 |
| 205281376 | NOVAIR PLUS | 18EVANVO | 18EVANVI | -25 |
| 205421170 | NOVAIR PLUS | 09EVANVO | 09EVANVI | -25 |
| 205281377 | NOVAIR PLUS | 24EVANVO | 24EVANVI | -25 |
| 205281379 | NOVAIR PLUS | 09EVANVO | 09EVCNVI | -25 |
| 9085568 | OUELLET | OTP-C09000-E | OTP-C09000-I | -25 |
| 9085569 | OUELLET | OTP-C12000-E | OTP-C12000-I | -25 |
| 9085570 | OUELLET | OTP-C18000-E | OTP-C18000-I | -25 |

| | | | | |
|-----------|--------------|--------------------|--------------------|-----|
| 9085571 | OUELLET | OTP-C24000-E | OTP-C24000-I | -25 |
| 202110483 | Ouelllet/ACD | UHD09KCH38S-O | UHD09KCH38S-I | -30 |
| 202110484 | Ouelllet/ACD | UHD12KCH31S-O | UHD12KCH31S-I | -30 |
| 202110485 | Ouelllet/ACD | UHD18KCH25S-O | UHD18KCH25S-I | -30 |
| 202409832 | Ouelllet/ACD | UHD09KCH38SB-O | UHD09KCH38SB-I | -30 |
| 202132789 | Ouelllet/ACD | UHD24KCH22S-O | UHD24KCH22S-I | -30 |
| 7958198 | PANASONIC | CU-E9RKUA | CS-E9RKUAW | -25 |
| 7958199 | PANASONIC | CU-E12RKUA | CS-E12RKUAW | -25 |
| 7958200 | PANASONIC | CU-E18RKUA | CS-E18RKUAW | -25 |
| 8860533 | PANASONIC | CU-XE9SKUA | CS-XE9SKUA | -26 |
| 201900210 | PANASONIC | CU-XE12SKUA-1 | CS-XE12SKUA-1 | -26 |
| 201900302 | PANASONIC | CU-XE15SKUA-1 | CS-XE15SKUA-1 | -26 |
| 205047851 | PANASONIC | CU-XE9WKUA | CS-XE9WKUAW | -26 |
| 205047852 | PANASONIC | CU-XE12WKUA | CS-XE12WKUAW | -26 |
| 205047853 | PANASONIC | CU-XE15WKUA | CS-XE15WKUAW | -26 |
| 205047854 | PANASONIC | CU-XE18WKUA | CS-XE18WKUAW | -26 |
| 205047855 | PANASONIC | CU-XE24WKUA | CS-XE24WKUAW | -26 |
| 8177079 | PAYNE | DLCAHB09K1A | DLFAHH09K1A | -30 |
| 8177088 | PAYNE | DLCAHB12K1A | DLFAHH12K1A | -30 |
| 8177097 | PAYNE | DLCAHB18K1A | DLFAHH18K1A | -30 |
| 201753410 | PAYNE | 38MPRAQ09AA3 | DHMPHAQ09XA3 | -25 |
| 201753413 | PAYNE | 38MPRAQ12AA3 | DHMPHAQ12XA3 | -25 |
| 201846966 | PAYNE | 38MAQB09R--1 | DHMSHAQ09XA1 | -25 |
| 201846967 | PAYNE | 38MAQB12R--1 | DHMSHAQ12XA1 | -25 |
| 201846968 | PAYNE | 38MAQB09R--3 | DHMSHAQ09XA3 | -25 |
| 201846969 | PAYNE | 38MAQB12R--3 | DHMSHAQ12XA3 | -25 |
| 201846970 | PAYNE | 38MAQB18R--3 | DHMSHAQ18XA3 | -25 |
| 201846971 | PAYNE | 38MAQB24R--3 | DHMSHAQ24XA3 | -25 |
| 201846972 | PAYNE | 38MAQB09R--3 | 40MBCQ09---3 | -25 |
| 201846973 | PAYNE | 38MAQB12R--3 | 40MBCQ12---3 | -25 |
| 201846974 | PAYNE | 38MAQB18R--3 | 40MBCQ18---3 | -25 |
| 201846975 | PAYNE | 38MAQB09R--3 | 40MBDQ09---3 | -25 |
| 201846976 | PAYNE | 38MAQB12R--3 | 40MBDQ12---3 | -25 |
| 201846977 | PAYNE | 38MAQB18R--3 | 40MBDQ18---3 | -25 |
| 201846978 | PAYNE | 38MAQB24R--3 | 40MBDQ24---3 | -25 |
| 201846979 | PAYNE | 38MAQB12R--3 | 40MBFQ12---3 | -25 |
| 201846980 | PAYNE | 38MAQB18R--3 | 40MBFQ18---3 | -25 |
| 206188267 | PAYNE | 38MARBQ24AA3 | 40MBAAQ24XA3 | -30 |
| 206350358 | PAYNE | 38MARBQ24AA3 | 40MBDQ24---3 | -30 |
| 206350315 | PAYNE | 38MARBQ18AA3 | DHMAHBQ18XA3 | -30 |
| 206350354 | PAYNE | 38MARBQ18AA3 | 40MBCQ18---3 | -30 |
| 206350355 | PAYNE | 38MARBQ18AA3 | 40MBDQ18---3 | -30 |
| 206350356 | PAYNE | 38MARBQ18AA3 | 40MBFQ18---3 | -30 |
| 206400656 | PAYNE | 38MARBQ18AA3 | DHMSHAQ18XA3 | -30 |
| 206350351 | PAYNE | 38MARBQ12AA3 | 40MBCQ12---3 | -30 |
| 9856844 | PERFECTAIRE | 1PAMSHH09-SZO-25 | 1PAMSHH09-SZW-25 | -30 |
| 9856845 | PERFECTAIRE | 1PAMSHH12-SZO-22.5 | 1PAMSHH12-SZW-22.5 | -25 |

| | | | | |
|-----------|-------------|--------------------|--------------------|-----|
| 9856849 | PERFECTAIRE | 1PAMSHH24-SZO-20.5 | 1PAMSHH24-SZW-20.5 | -30 |
| 9857571 | PERFECTAIRE | 1PAMSHH18-SZO-22.5 | 1PAMSHH18-SZW-22.5 | -30 |
| 202140575 | PERFECTAIRE | 2PAMSHH18-SZO-20 | 2PAMSHH18-SZW-20 | -30 |
| 8203107 | SAMSUNG | AC030JXSCCH/AA | AC030JN4DCH/AA | -25 |
| 8203116 | SAMSUNG | AC036JXSCCH/AA | AC036JN4DCH/AA | -25 |
| 8203117 | SAMSUNG | AC030JXSCCH/AA | AC030JNHDCH/AA | -25 |
| 8203122 | SAMSUNG | AC036JXSCCH/AA | AC036JNHDCH/AA | -25 |
| 9035283 | SAMSUNG | AR09KSWSPWKX | AR09KSWSPWKN | -25 |
| 9035284 | SAMSUNG | AR12KSWSPWKX | AR12KSWSPWKN | -25 |
| 201993481 | SAMSUNG | AR18NSWSPWKX | AR18NSWSPWKN | -25 |
| 202022716 | SAMSUNG | AR24NSWSPWKX | AR24NSWSPWKN | -25 |
| 202087971 | SAMSUNG | AC030JXSCCH/AA | AC030NN4DCH/AA | -25 |
| 202087972 | SAMSUNG | AC036JXSCCH/AA | AC036NN4DCH/AA | -25 |
| 205132627 | SAMSUNG | AR12TSFACWKX | AR12TSFABWKN | -25 |
| 205132628 | SAMSUNG | AR09TSFACWKX | AR09TSFABWKN | -25 |
| 205132633 | SAMSUNG | AR24TSFACWKX | AR24TSFABWKN | -25 |
| 205132635 | SAMSUNG | AR18TSFACWKX | AR18TSFABWKN | -25 |
| 8797149 | SENVILLE | SENA/09HF/OZ | SENA/09HF/IZ | -30 |
| 8797150 | SENVILLE | SENA/12HF/OZ | SENA/12HF/IZ | -30 |
| 8797151 | SENVILLE | SENA/18HF/OZ | SENA/18HF/IZ | -30 |
| 8796398 | SHARP | AE-X12THU | AY-XP12THU | -27 |
| 8177083 | TEMPSTAR | DLC AHB09K1A | DLFAHH09K1A | -30 |
| 8177092 | TEMPSTAR | DLC AHB12K1A | DLFAHH12K1A | -30 |
| 8177101 | TEMPSTAR | DLC AHB18K1A | DLFAHH18K1A | -30 |
| 201835748 | TEMPSTAR | DLC PRAH09AAK | DLF PHAH09XAK | -25 |
| 201835750 | TEMPSTAR | DLC PRAH12AAK | DLF PHAH12XAK | -25 |
| 201835763 | TEMPSTAR | DLC SRAH09AAJ | DLF SHAH09XAJ | -25 |
| 201835765 | TEMPSTAR | DLC SRAH12AAJ | DLF SHAH12XAJ | -25 |
| 201835767 | TEMPSTAR | DLC SRAH09AAK | DLF SHAH09XAK | -25 |
| 201835769 | TEMPSTAR | DLC SRAH12AAK | DLF SHAH12XAK | -25 |
| 201835771 | TEMPSTAR | DLC SRAH18AAK | DLF SHAH18XAK | -25 |
| 201835773 | TEMPSTAR | DLC SRAH24AAK | DLF SHAH24XAK | -25 |
| 201835800 | TEMPSTAR | DLC SRAH09AAK | DLFSDAH09XAK | -25 |
| 201835802 | TEMPSTAR | DLC SRAH09AAK | DLFSCAH09XAK | -25 |
| 201835804 | TEMPSTAR | DLC SRAH12AAK | DLFSCAH12XAK | -25 |
| 201835806 | TEMPSTAR | DLC SRAH12AAK | DLFSFAH12XAK | -25 |
| 201835808 | TEMPSTAR | DLC SRAH12AAK | DLFSDAH12XAK | -25 |
| 201835810 | TEMPSTAR | DLC SRAH18AAK | DLFSFAH18XAK | -25 |
| 201835812 | TEMPSTAR | DLC SRAH18AAK | DLFSCAH18XAK | -25 |
| 201835814 | TEMPSTAR | DLC SRAH24AAK | DLFSDAH24XAK | -25 |
| 201835824 | TEMPSTAR | DLC SRAH18AAK | DLFSDAH18XAK | -25 |
| 9108745 | TOSOT | TW09HQ2C2DO | TW09HQ2C2DI | -25 |
| 9108746 | TOSOT | TW12HQ2C2DO | TW12HQ2C2DI | -25 |
| 9108747 | TOSOT | TW18HQ2C2DO | TW18HQ2C2DI | -25 |
| 9108748 | TOSOT | TW24HQ2C2DO | TW24HQ2C2DI | -25 |
| 10062018 | TOSOT | TW09HQ3D6DO | TW09HQ3D6DI | -30 |
| 10062019 | TOSOT | TW12HQ3D6DO | TW12HQ3D6DI | -30 |

| | | | | |
|-----------|---------|-----------------|-----------------|-----|
| 10062020 | TOSOT | TW18HQ3D6DO | TW18HQ3D6DI | -25 |
| 10062021 | TOSOT | TW24HQ3D6DO | TW24HQ3D6DI | -30 |
| 202126395 | TOSOT | TW09HQ2A3DO | TW09HQ2A3DI | -25 |
| 202134392 | TOSOT | TW12HQ2A3DO | TW12HQ2A3DI | -25 |
| 202134393 | TOSOT | TW18HQ2A3DO | TW18HQ2A3DI | -25 |
| 202134394 | TOSOT | TW24HQ2A3DO | TW24HQ2A3DI | -25 |
| 9150121 | TRANE | 4TXK3809A10NU** | 4MXW3809A10NU** | -30 |
| 9150123 | TRANE | 4TXK3812A10NU** | 4MXW3812A10NU** | -30 |
| 9150125 | TRANE | 4TXK3818A10NU** | 4MXW3818A10NU** | -30 |
| 9150127 | TRANE | 4TXK3824A10NU** | 4MXW3824A10NU** | -30 |
| 204340354 | TRANE | 4TXK3809B10NU** | 4MXW3809B10NU** | -30 |
| 201903173 | WABBAN | BB12HQ3D6DO | BB12HQ3D6DI | -30 |
| 9085347 | WINDAIR | EWH12HA1A/O | EWH12HA1A/I | -25 |
| 9085348 | WINDAIR | EWH18HA1A/O | EWH18HA1A/I | -25 |
| 9085349 | WINDAIR | EWH24HA1A/O | EWH24HA1A/I | -25 |